

## Message Text

CONFIDENTIAL

PAGE 01 STATE 031784

11

ORIGIN SY-05

INFO OCT-01 ISO-00 /006 R

DRAFTED BY A/SY/T: JLECHEVET:GS

APPROVED BY A/SY/T: DGFISCHER, CHIEF

DESIRED DISTRIBUTION

SY/FO/EUR

----- 128491

R 092317Z FEB 76

FM SECSTATE WASHDC

TO AMEMBASSY BUDAPEST

C O N F I D E N T I A L STATE 031784

FOR RSO

E.O. 11652: GDS

TAGS:ASEC

SUBJECT: AUTOSCAN PRINTER FAILURE

REF: (A) BUDAPEST 00164, (B) BUDAPEST 1/76 REPORT,  
(C) BUDAPEST 00402

1. APOLOGIES FOR THE DELAY IN ANSWERING.
2. THE MOST LIKELY PROBLEM IS THAT THE PLUS 5V SUPPLY IS  
BEING OVERWORKED BY ANOTHER COMPONENT.
3. REMOVE ALL CIRCUIT BOARDS ACCESSIBLE FROM THE FRONT  
PANEL AND REPLACE FS 3 WITH A 6 AMPERE FUSE. IF FS 3  
DOES NOT BLOW, INSERT BOARDS ONE AT A TIME UNTIL FS 3  
BLOWS.
4. REPORT RESULTS OF THIS TEST ASAP. NEW UNIT CAN BE  
POUCHED, BUT WOULD PREFER TO FIELD ISOLATE THE PROBLEM  
TO A SINGLE COMPONENT. INGERSOLL

CONFIDENTIAL

NNN



## Message Attributes

**Automatic Decaptioning:** X  
**Capture Date:** 01 JAN 1994  
**Channel Indicators:** n/a  
**Current Classification:** UNCLASSIFIED  
**Concepts:** n/a  
**Control Number:** n/a  
**Copy:** SINGLE  
**Draft Date:** 09 FEB 1976  
**Decaption Date:** 01 JAN 1960  
**Decaption Note:**  
**Disposition Action:** RELEASED  
**Disposition Approved on Date:**  
**Disposition Authority:** MartinML  
**Disposition Case Number:** n/a  
**Disposition Comment:** 25 YEAR REVIEW  
**Disposition Date:** 28 MAY 2004  
**Disposition Event:**  
**Disposition History:** n/a  
**Disposition Reason:**  
**Disposition Remarks:**  
**Document Number:** 1976STATE031784  
**Document Source:** CORE  
**Document Unique ID:** 00  
**Drafter:** JLECHEVET:GS  
**Enclosure:** n/a  
**Executive Order:** GS  
**Errors:** N/A  
**Film Number:** D760050-0033  
**From:** STATE  
**Handling Restrictions:** n/a  
**Image Path:**  
**ISecure:** 1  
**Legacy Key:** link1976/newtext/t19760266/aaaacgkp.tel  
**Line Count:** 52  
**Locator:** TEXT ON-LINE, ON MICROFILM  
**Office:** ORIGIN SY  
**Original Classification:** CONFIDENTIAL  
**Original Handling Restrictions:** n/a  
**Original Previous Classification:** n/a  
**Original Previous Handling Restrictions:** n/a  
**Page Count:** 1  
**Previous Channel Indicators:** n/a  
**Previous Classification:** CONFIDENTIAL  
**Previous Handling Restrictions:** n/a  
**Reference:** 76 BUDAPEST 164  
**Review Action:** RELEASED, APPROVED  
**Review Authority:** MartinML  
**Review Comment:** n/a  
**Review Content Flags:**  
**Review Date:** 29 APR 2004  
**Review Event:**  
**Review Exemptions:** n/a  
**Review History:** RELEASED <29 APR 2004 by SmithRJ>; APPROVED <18 AUG 2004 by MartinML>  
**Review Markings:**

Margaret P. Grafeld  
Declassified/Released  
US Department of State  
EO Systematic Review  
04 MAY 2006

**Review Media Identifier:**  
**Review Referrals:** n/a  
**Review Release Date:** n/a  
**Review Release Event:** n/a  
**Review Transfer Date:**  
**Review Withdrawn Fields:** n/a  
**Secure:** OPEN  
**Status:** NATIVE  
**Subject:** AUTOSCAN PRINTER FAILURE  
**TAGS:** ASEC  
**To:** BUDAPEST  
**Type:** TE  
**Markings:** Margaret P. Grafeld Declassified/Released US Department of State EO Systematic Review 04 MAY 2006